

Issues

SERVICE BULLETIN No. BB/42, BB-S/6, AB20


- 1. WITH REFERENCE TO:** Hot air balloons Kubicek and Aerotechnik operated with the baskets K10 and K25P.
(EASA Type Certificates no. BA.001, BA.002, BA.003, BA.004, BA.017)
- 2. REASON:** Reduction of the maximum occupancy of the baskets K10 and K25P for improving safety and due to latest requirements.
- 3. REQUIRED ACTION:** Update the manuals to the latest approved revision:

For all Aerotechnik envelopes and Kubicek BB and BB-S envelopes of serial numbers up to 639:
 - Flight Manual (*doc. no. B.0102, revision 22*), or
 - Letová příručka (*doc. no. B.0101, revision 22*),
For Kubicek BB and BB-S envelopes of serial numbers 640 and higher:
 - Flight Manual (*doc. no. B.2102, revision 12*)
- 4. DEADLINE FOR ACTION:** Prior to next flight
- 5. ACTION CARRIED OUT BY:** Owner / operator
- 6. INDUCED COST COVERED:** Owner / operator
- 7. NECESSARY MATERIAL:** The above mentioned manuals.
- 8. PROCESS:** Download the respective documents from the Kubicek Balloons website, print them and replace the manuals originally supplied by the new revision.
- 9. BULLETIN TAKES EFFECT:** 24 Nov 2011
- 10. ENCLOSURES:** None

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček, technical director



Date: 24 Nov 2011