

Issues

SERVIS BULLETIN No. BB/51

- 1. WITH REFERENCE TO:** All hot-air balloons Kubicek and Aerotechnik operated with Ignis 2-units burner (s/n 300-301 up to 469-470) and all hot-air balloons produced by any other manufacturer combined with Ignis 2-units burners (s/n 300-301 up to 469-470)
- 2. REASON:** Weld crack of suspension of Ignis 2-units burner
Example see below – Enclosure 1
- 3. REQUIRED ACTION:** Replacement of suspension of the burner units
- 4. DEADLINE FOR ACTION:** May 31, 2018
- 5. ACTION CARRIED OUT BY:** Maintenance organization authorized by national regulations
- 6. INDUCED COST COVERED:** Owner/Operator
- 7. NECESSARY MATERIAL:** New burner suspension, part number.: 53128.00
To specify a serial number of the burner is necessary when placing your order.
- 8. PROCESS:** Replace the burner suspension. Follow the instructions given in appropriate Maintenance Manual.
- 9. BULLETIN TAKES EFFECT:** May 31, 2017
- 10. ENCLOSURES:** 1. Example of a weld crack of suspension of Ignis 2-units burner

Technical content of this document is approved under the authority of DOA No. EASA.21J.277

On behalf of BALÓNY KUBÍČEK spol. s r.o.:

Ing. Petr Kubíček, technical director

Date: 26 May 2017



Enclosure 1
Example of a weld crack of suspension of Ignis 2-units burner

