

issues

SERVICE INSTRUCTION no. 2012/3 – revision 1

Installing of basket wire stopper

With reference to: Single wire baskets – K7, K10, K11, K13S

During windy inflation basket karabiner can be twisted so that the burner rod is detached from the burner socket. In that case the inflation must be interrupted and the burner frame returned to its original position. The effect is shown on the following pictures.



In order to prevent this issue we highly recommend installation of „Basket wire stopper“, order no. 54725.00. Just put on the karabiner the rubber eye as seen on the following picture.



The stopper holds the karabiner in its position so the karabiner cannot be twisted.



Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

For KUBÍČEK BALLOONS

Petr Kubíček, technical director

A handwritten signature in black ink, appearing to be 'Petr Kubíček'.

Datum: **04 October 2013**