

KUBÍČEK

issues

SERVICE INSTRUCTION no. 2024/01

Replacing of control line carabiners without operating line jack

Cause: Securing carabiner to the end of a control line with a knot instead of an operating line jack.

With reference to: Kubíček envelopes, all serial numbers.

Action: When exchanging carabiners on the end of any control line (RV as well as DS/FDS system), it is possible to replace the operating line jack (part No. 2856.00) with the safety turnback knot as per Maintenance Manual B.3202.



In Brno, 29th April 2024

A handwritten signature in blue ink, appearing to be 'Petr Kubíček', is written on the page.

Petr Kubíček, Head of design organisation

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.